







016296-07

GEZE



1 | 2




3



4









5



Fz 100 Fz 101

1   Lb = G - 318





14

130738

14

FZ	a; LA1, LA2, LA3	LA4 [mm]
FZ 100	130738	G - 15
FZ 101	130738	221

