





TS 5000 ECLINE




144856-06

GEZE




5 mm

A









$a \leq 1250 \text{ mm}$









B





$a \leq 1250 \text{ mm}$



4x
 $\varnothing 5$
4x
M5




4x
 $\varnothing 5$
4x
M5




4x
M5x45


1




2




3




4




5



6



7



8

