



Boxer EFS
4-6



155727-01

GEZE

Tools and Materials:

- 3 mm screwdriver
- 4 mm screwdriver
- 5 mm screwdriver
- 2x 2x M8x14 screws
- 2x 2x M5x14 screws
- 4x 4x M5x20 screws
- 4x 4x M5x14 screws

Warnings and Notes:

- Read manual (i icon)
- Warning (triangle with exclamation mark)
- Wear gloves (gloves icon)
- Wear safety glasses (goggles icon)
- Unpack (box icon)
- Use tools (wrench and screwdriver icon)

1

4 mm

20,7

12 30

3

4

2

4 mm

2x M8x14

3

3 mm

1-2 Nm

4

3 mm

ID 53123

1,5 Nm

1,5 Nm

5

3 mm

ID 53123

3 Nm

3 Nm

6

24 V DC

4x 5x20

4x M5x14

7

2x 4,5x30

2x M5x14

